

## DESCRIPTION

Stoody “S” Flux is an active fused flux designed for used with Stoody Submerged Arc Welding Wires (other than the ThermaClad<sup>®</sup> wires). As the deposit composition is significantly altered from the wire composition, care should be exercised in the matching of this flux to the right wire.

## STANDARD SIZES & PACKAGING

“S” Flux is available in 50# Bags (Part Number: 11008400)

### **Stoody Company**

5557 Nashville Road • Bowling Green, KY 42101  
1-800-227-9333

PDS-FL-002  
Revision 0  
08/06/02

Notice: The information contained or otherwise referenced herein is presented only as “typical”, without guarantee or warranty. Stoody expressly disclaims any liability from any reliance thereon. Typical data are those obtained when welded and tested in accordance with Stoody’s internal procedures. Other tests and procedures may produce different results. No data is to be construed as a recommendation for any welding condition or technique not controlled by Stoody.